

# Carrier 19C 1200 ton Centrifugal Chiller Repair Case Study



## Facility:

Class "A" High Rise

## Repair Parameters:

Inlet guide vanes were seized

## Repair Challenges:

No room for rigging and had to custom build a gantry to rig

## Repair Rigging & Tools: Custom

## Repair Time / Constraints / Opportunities:

Machines have to be repaired in place because they are located on the 36<sup>th</sup> floor



ThermaServe Mechanical Systems Services  
6676-1 Columbia Park Dr. South \* Jacksonville, FL 32258 \* [www.thermaserve.com](http://www.thermaserve.com)  
T (904) 260-8002 \* F (904) 260-8004 \* [thermaserveinc@bellsouth.net](mailto:thermaserveinc@bellsouth.net)  
FL#CMC057091 \* GA#CN209367

