

Carrier 19EB Centrifugal Chiller Repair Case Study



Facility:

Class "A" High Rise

Repair Parameters:

Eight Year Stop Major –
mechanical inspection




Repair Challenges:

Low overhead

Repair Rigging & Tools: Creative rigging procedures were required

Repair Time / Constraints / Opportunities:

Detected bearing wear and therefore able to replace during inspection.



ThermaServe Mechanical Systems Services
6676 Columbia Park Dr. South * Jacksonville, FL 32258 * www.thermaserve.com
T (904) 260-8002 * F (904) 260-8004 * thermaserveinc@bellsouth.net
FL#CMC057091 * GA#CN209367

